

Safety Alert

From the International Association of Drilling Contractors

ALERT 11 - 12

DROPPED OBJECT – LOW PRESSURE RISER DROPPED 50 FEET

WHAT HAPPENED:

A low pressure riser weighing four (4) tons dropped 50 feet (15 meters) from the diverter onto the platform below. The 25 foot (7.84 meter) long extension joint, or low pressure riser was secured in the rotary table in the diverter spider clamp and the diverter housing was mated to the extension and the securing ring made up tight using the C- spanner and hammer. Once it was secure, the complete assembly was picked up enough to release the spider clamp. The assembly was raised through the rotary table with two roughnecks guiding it to avoid any possible hang ups. No hang ups were noted and the weight indicator was closely monitored. At approximately four feet from clearing the rotary table, part of the assembly dropped down through the rotary table landing 50 feet (15 meters) to the platform below.



WHAT CAUSED IT:

The pin end thread had not been fully mated up during a recent 3 Party (non OEM) onshore overhaul. This allowed fluid to migrate into the threaded area causing corrosion and eventual failure of the thread.



Condition of threads on parted diverter

CORRECTIVE ACTIONS: To address this incident, this company did the following:

- Before carrying out any overhaul and integrity testing ensure the correct Operating Service Procedure (OSP) is obtained for the part number of the equipment.
- OEM procedures are to be followed by end users and all 3rd Parties.
- OEM has been notified of the incident and been asked to provide professional support as appropriate.

The Corrective Actions stated in this alert are one company's attempts to address the incident, and do not necessarily reflect the position of IADC or the IADC HSE Committee.