

Safety Alert

From the International Association of Drilling Contractors

ALERT 08 - 20

IMPROPER LIFTING PRACTICE (LTI)

WHAT HAPPENED:

While rigging up the V-door during a rig move, the driller was supervising two floormen who were assigned to install the V-door pins. The crane was holding the V-door in an inclined position and lowering it under the driller's signals. The handrail attached to the V-door steps became stuck against the air hoist on the rig floor (driller did not notice it). The IP was installing the middle pin and another floorman was installing another pin beside him, the driller was helping them and giving signal to the crane operator at the same time to lower the V-door slightly to facilitate the installation of the pin. Suddenly the handrail got free from the air hoist and moved away fast and the V- door gate support hit the injured person's (IP's) left knee. The IP sustained a hematoma in his left knee and put his leg in cast for 2 weeks.

WHAT CAUSED IT:

- Inadequate supervision and poor communication, as the driller gave a signal to the crane operator to lower the V-door in, was not observing the load.
- At the same time the IP was still close and installing the pin.
- Driller acted as banksman (signal man) and lift supervisor, thus not giving himself full view of the work place and he failed to see the handrail hung up on the air winch.
- There was a change of design when it was decided to weld the gate support of the V-door. The Management of Change (MOC) process was not followed.
- Welding the V-door gate allowed the hand rail to get tangled with the air hoist on the rig floor.
- The Safe Job Assessment (SJA) did not address the potential of the load getting hung up on the air winch.

CORRECTIVE ACTIONS: To address this incident, this company did the following:

- Proper SJA to be issued and communicated with rig crews in the pre-job meeting.
- Improve lifting competency of the crew and supervisors.

The Corrective Actions stated in this alert are one company's attempts to address the incident, and do not necessarily reflect the position of IADC or the IADC HSE Committee.



Safety AlertFrom the International Association of Drilling Contractors



Air hoist and hand rail after installation

The Corrective Actions stated in this alert are one company's attempts to address the incident, and do not necessarily reflect the position of IADC or the IADC HSE Committee.