


# **THE RENEWABLE BIT EXPLODE YOUR PROFIT**

**DO NOT PULL THAT DRILL STRING  
TO CHANGE BITS. SAVE DAYS FOR  
PRODUCTIVE DRILLING.**


Worn Bit. ROP Down. Need To Change.




Pull The Worn Bit Up 30 Feet.




Punch In The Code On Your Surface Controller.  
Blow The Worn Tip Off the Drill String




The Worn Tip Is Now Separated And Lies  
At The Bottom Of The Bore Hole




Punch In Another Code On Your Surface Controller  
To Explode And Fragment The Worn Tip.



The Old Worn Tip Is Now Rubble.  
A Brand New Sharp Tip Is Now Ready



Lower The Drill String And Flush  
The Old Tip Fragments Away





Resume Progress With A Brand, New,  
Sharp Drill Tip. Not Days...15 Minutes.

