

THE DRILLER NOTICED LOOSE BOLTS IN THE SUBSTRUCTURE-AND SAID: TIGHTEN THEM! CHEATERS HAD TO BE USED.



TROUBLE WAS- THEY TWISTED OFF BEFORE THEY COULD BE MADE UP- THERE WAS A REASON -



THEN CAME THE ORDER: TIGHTEN THEM ALL OR TWIST THEM OFF! MOST WERE BAD -



RESULT: THE SUBSTRUCTURE GOT A LOT OF NEW BOLTS - THEN A LOT OF PAINT -



INTERNATIONAL ASSOCIATION OF DRILLING CONTRACTORS
P.O. BOX 4287 HOUSTON TX 77210-4287